

We All See the Façade of Saint Paul's.....
But What Lies Within???


.....Historic, Irreplaceable, and Beautiful 19TH
Century Architectural Details!



Nearly priceless stained-glass windows...some from Tiffany



Tiffany Stained Glass



STAINED GLASS WINDOWS



A Magnificent Chapel with Pipe Organ, Stained Glass Windows, and Hand-Carved Oak Pews and Oak Trim




Grand Doorways and Entrances in the Chapel



Chapel as it Once Was



Chapel in 1966



The original Chapel (partially restored in 1966).

Chapel



Chapel: Carved Oak and Stained Glass



19th Century Ironwork // Staircase Railings



19th Century Ironwork // Staircase Railings



Sigillum 1985
Yearbook

19th Century Ironwork ... Staircase Railings



Iron Railings and Oak Paneling



Iron Railings / Tiled Walls



Iron Railings and Oak Paneling



Iron Railings and Oak Paneling



Thomas Minton Tile Work Staffordshire, England



Thomas Minton Tile Work Tile Floors and Tile Walls



Tile Floors and Tile Walls
Arch-top Transom Windows
6-panel Oak Doors



Magnificent Hand-carved Oak Fireplace



Beautiful Parlors and Foyers.... Solid Oak Trim and Panels



Beautiful Parlors and Foyers.... Solid Oak Trim and Panels



12 Panel Oak Doors Crystal Chandeliers



Solid Oak -- Grand Entrancesways



As it Once Was and Can Be Again!!



The East Parlor.

Original Parlors



Original Parlor Rooms



Assorted Image Credits: Bellmer, Alvey, Village Archives, GCNEWS
For Additional exterior Images / See: GC Patch.... <https://patch.com/new-york/gardencity/91-st-pauls-school-2>

End